



Aircraft Status



Aircraft status report was compiled by:

Kalahari Air Services

Tel: (267) 3951804
Fax: (267) 3912015
Address: P.O Box 41278
Gaborone
Botswana

KASAC Hangar No1
Seretse Khama International
Airport
Gaborone

Note: All items included in this report

Aircraft status report generated for:

Registration:

A2-HAN

BELL HELICOPTER TEXTRON 206B

Airframe status Monthly usage

Hours:	9,870.00	55
Cycles:	10,761	60
Landings:	0	0

Customer

Company: OKAVANGO HELICOPTERS
Contact:
Tel:
Fax:
Address: PRIVATE BAG 361
MAUN.
BOTSWANA

Report data last updated: 2008/02/19

The aircraft Status program is a good faith effort by AvData software to track and trace the maintenance history of a particular aircraft component. However this listing may not be represented as 100% accurate or all inclusive and the legal onus for such maintenance remains with the owner/operator in terms of the CAR's.



Aircraft Status



Aircraft: A2-HAN Component: 2350

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: BELL JETRANGER

Description / Part	Installed	Frequency	To Go	When Due	Expected due
--------------------	-----------	-----------	-------	----------	--------------

Heading

100 HOUR INSPECTION Inspect					
	9,813.25h	100.00h	43.00h	9,913.00h	2008/03/14
100 HOUR INSPECTION Inspect					
	2007/12/21	6m	4m	2008/06/21	2008/06/21
200 HOUR INSPECTION Inspect					
	9,716.40h	200.00h	46.00h	9,916.00h	2008/03/15
300 HOUR INSPECTION					
	9,615.60h	300.00h	46.00h	9,916.00h	2008/03/15
12 MONTH INSPECTIONS Inspect					
	2008/01/24	12m	11m	2009/01/23	2009/01/23
24 MONTH INSPECTIONS Inspect					
	2008/01/24	24m	23m	2010/01/23	2010/01/23
C OF A INSPECTION Inspect					
	2008/01/24	12m	11m	2009/01/23	2009/01/23
ELT BATTERY LIFE Replace					
	2007/12/21	24m	22m	2009/12/20	2009/12/20
RE WIEGH Calibrate					
	2006/03/02	36m	12m	2009/03/02	2009/03/02
PITOT STATIC CHECK Calibrate					
	2008/01/24	12m	11m	2009/01/23	2009/01/23
COMPASS SWING Calibrate					
	2008/01/24	6m	5m	2008/07/25	2008/07/25
GRIP ASSY OVERHAUL Overhaul					
Part:206-010-152-003U S/N:HBFS-1160	9,813.40h	1,200.00h	1,143.00h	11,013.00h	2009/11/12
GRIP ASSY RETIRE Replace					
Part:206-010-152-003U S/N:HBFS 1160	9,522.50h	4,800.00h	4,452.00h	14,322.00h	2014/11/16
GRIP ASSY OVERHAUL Overhaul					
Part:206-010-152-003U S/N:HBFS-1167	9,813.40h	1,200.00h	1,143.00h	11,013.00h	2009/11/12
GRIP ASSY RETIRE Replace					
Part:206-010- 152-003U S/N:HBFS-1167	9,522.50h	4,800.00h	1,976.00h	11,846.00h	2011/02/16
M/R BLADE ASSY Replace					
Part:206-010-200-133 S/N:TKK 7143	9,243.00h	5,000.00h	4,373.00h	14,243.00h	2014/10/03
M/R BLADE ASSY Replace					
Part:206-010-200-033 S/N:A3557	7,867.10h	5,000.00h	2,997.00h	12,867.00h	2012/09/02
M/R HUB ASSY Overhaul					
Part:206-011-100-021 S/N:RILM11671	9,552.30h	1,200.00h	882.00h	10,752.00h	2009/06/21
TRUNION ASSY O/H Overhaul					
Part:206-011-113-103 S/N:HB 2581	9,522.50h	1,200.00h	852.00h	10,722.00h	2009/06/04
MR YOKE O/H Overhaul					
Part:206-010-101-129	9,522.90h	1,200.00h	853.00h	10,723.00h	2009/06/05
RETENTION STRAP Overhaul					
Part:206-011-154-105	2006/08/17	24m	6m	2008/08/16	2008/08/16



Aircraft Status



Aircraft: A2-HAN Component: 2350

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: BELL JETRANGER

Description / Part	Installed	Frequency	To Go	When Due	Expected due
--------------------	-----------	-----------	-------	----------	--------------

Heading

S/N:LPFS22440

RETENTION STRAP Replace

Part:206-011-154-105	2006/08/17	24m	6m	2008/08/16	2008/08/16
----------------------	------------	-----	----	------------	------------

S/N:LPFS22355

RETENTION STRAP Replace

Part:206-011-154-105	9,374.20h	1,200.00h	704.00h	10,574.00h	2009/03/14
----------------------	-----------	-----------	---------	------------	------------

S/N:LPFS22440

RETENTION STRAP Replace

Part:206-011-154-105	9,374.20h	1,200.00h	704.00h	10,574.00h	2009/03/14
----------------------	-----------	-----------	---------	------------	------------

S/N:LPFS22440

RETENTION PIN Replace

Part:206-010-123-003	9,552.30h	1,200.00h	882.00h	10,752.00h	2009/06/21
----------------------	-----------	-----------	---------	------------	------------

S/N:DIFS-19060

RETENTION PIN Replace

Part:206-010-123-003	9,522.90h	1,200.00h	853.00h	10,723.00h	2009/06/05
----------------------	-----------	-----------	---------	------------	------------

S/N:DIFS-19939

✘ RETENTION PIN - Not active on this component

✘ RETENTION PIN - Not active on this component

RETENTION FITTING Replace

Part:206-11-140-001 S/N:DIFS1196	9,813.40h	2,500.00h	2,443.00h	12,313.00h	2011/11/01
----------------------------------	-----------	-----------	-----------	------------	------------

RETENTION FITTING Replace

Part:206-11-140-001 S/N:DIFS1168	9,813.40h	2,500.00h	2,443.00h	12,313.00h	2011/11/01
----------------------------------	-----------	-----------	-----------	------------	------------

✘ RETENTION FITTING - Not active on this component

✘ RETENTION FITTING - Not active on this component

LATCH BOLT Replace

Part:206-011-260-103 S/N:DI17097	8,662.90h	2,500.00h	1,293.00h	11,163.00h	2010/02/03
----------------------------------	-----------	-----------	-----------	------------	------------

LATCH BOLT Replace

Part:206-011-260-103 S/N:DI17241	8,662.90h	2,500.00h	1,293.00h	11,163.00h	2010/02/03
----------------------------------	-----------	-----------	-----------	------------	------------

TRUNION RETIRE Replace

Part:206-011-113-103 S/N:HB-2581	9,522.50h	4,800.00h	1,976.00h	11,846.00h	2011/02/16
----------------------------------	-----------	-----------	-----------	------------	------------

✘ TRUNION RETIRE - Not active on this component

MR MAST INSPECTION Inspect

Part:206-040-002-007 S/N:FAJF-09633	2008/01/24	12m	11m	2009/01/23	2009/01/23
-------------------------------------	------------	-----	-----	------------	------------

M/R MAST INSP Inspect

Part:206-040-002-007 S/N:FAJF-09633	9,243.00h	1,500.00h	873.00h	10,743.00h	2009/06/16
-------------------------------------	-----------	-----------	---------	------------	------------

M/R MAST O/H Overhaul

Part:206-040-002-007 S/N:FAJF-09633	9,243.00h	3,000.00h	2,373.00h	12,243.00h	2011/09/23
-------------------------------------	-----------	-----------	-----------	------------	------------

TRANSMISSION INSP Inspect

Part:206-040-002-25 S/N:BKW 11445	8,716.40h	1,500.00h	346.00h	10,216.00h	2008/08/28
-----------------------------------	-----------	-----------	---------	------------	------------

TRANSMISSION O/H Overhaul

Part:206-040-002-25 S/N:BKW 11445	7,492.30h	4,500.00h	2,122.00h	11,992.00h	2011/05/08
-----------------------------------	-----------	-----------	-----------	------------	------------



Aircraft Status



Aircraft: A2-HAN Component: 2350

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: BELL JETRANGER

Description / Part	Installed	Frequency	To Go	When Due	Expected due
--------------------	-----------	-----------	-------	----------	--------------

Heading

SWASHPLATE ASSY RET Replace

Part:206-010-450-011 S/N:RIJG 09974	9,592.50h	4,800.00h	4,522.00h	14,392.00h	2014/12/25
-------------------------------------	-----------	-----------	-----------	------------	------------

SUPPORT ASSY RETIRE Replace

Part:206-010-452--113 S/N:A-3183	9,522.50h	4,800.00h	4,452.00h	14,322.00h	2014/11/16
----------------------------------	-----------	-----------	-----------	------------	------------

SWASH PLATE SLEEVE Replace

Part:206-010-454-113 S/N:RE 9239	9,592.50h	4,800.00h	4,522.00h	14,392.00h	2014/12/25
----------------------------------	-----------	-----------	-----------	------------	------------

COLLECTIVE SLEEVE Replace

Part:206-010-454-109 S/N:RE 3384	9,592.50h	4,800.00h	4,522.00h	14,392.00h	2014/12/25
----------------------------------	-----------	-----------	-----------	------------	------------

✘ COLLECTIVE SLEEVE RT - Not active on this component

COLLECTIVE TUBE RET Replace

Part:206-001-194-001 S/N:TYFS 251	9,592.50h	4,800.00h	4,522.00h	14,392.00h	2014/12/25
-----------------------------------	-----------	-----------	-----------	------------	------------

COLLECTIVE LINK Replace

Part:206-010-407-001 S/N:1153	9,592.50h	4,800.00h	4,522.00h	14,392.00h	2014/12/25
-------------------------------	-----------	-----------	-----------	------------	------------

COLLECTIVE LEVER Replace

Part:206-010-467 -105 S/N:REFS 3583	9,522.90h	4,800.00h	4,453.00h	14,323.00h	2014/11/17
-------------------------------------	-----------	-----------	-----------	------------	------------

T/ ROTOR HUB ASSY Replace

Part:206-011-810-153 S/N:HB1983	9,813.40h	5,000.00h	4,943.00h	14,813.00h	2015/08/15
---------------------------------	-----------	-----------	-----------	------------	------------

T ROTOR HUB ASSY O/H Inspect

Part:206-011-810-125 S/N:HB1983	9,813.40h	2,500.00h	2,443.00h	12,313.00h	2011/11/01
---------------------------------	-----------	-----------	-----------	------------	------------

TAIL ROTOR BLADE Replace

Part:206-016-201-131 S/N:CS 12972	9,144.00h	2,500.00h	1,774.00h	11,644.00h	2010/10/27
-----------------------------------	-----------	-----------	-----------	------------	------------

TAIL ROTOR BLADE Replace

Part:206-016-201-135 S/N:CS 15749	9,813.40h	2,500.00h	2,443.00h	12,313.00h	2011/11/01
-----------------------------------	-----------	-----------	-----------	------------	------------

✘ TAIL ROTOR BLADE - Not active on this component

✘ TAIL ROTOR BLADE - Not active on this component

TAIL ROTOR OIL CHANG Replace

Part:BP 2380	9,813.40h	200.00h	143.00h	10,013.00h	2008/05/08
--------------	-----------	---------	---------	------------	------------

TRANSMISSION OIL Replace

Part:BP 2380	9,813.40h	200.00h	143.00h	10,013.00h	2008/05/08
--------------	-----------	---------	---------	------------	------------

FREE WHEEL UNIT INS Inspect

Part:206-040-270-003 S/N:BMB45234	8,944.00h	1,500.00h	574.00h	10,444.00h	2009/01/01
-----------------------------------	-----------	-----------	---------	------------	------------

FREE WHEELUNIT O/H Overhaul

Part:206-040-270-003 S/N:BMB45234	8,944.00h	3,000.00h	2,074.00h	11,944.00h	2011/04/11
-----------------------------------	-----------	-----------	-----------	------------	------------

CLUTCH Replace

Part:CL 42250-1 S/N:FD16334	8,944.00h	3,000.00h	2,074.00h	11,944.00h	2011/04/11
-----------------------------	-----------	-----------	-----------	------------	------------

T ROTOR G/BOX O/H Overhaul

Part:206-040-400-013 S/N:ALO 53006	8,997.00h	6,000.00h	5,127.00h	14,997.00h	2015/11/24
------------------------------------	-----------	-----------	-----------	------------	------------

T/ ROTOR DUPLEX BRG Replace

Part:206-040-410-103 S/N:ZV10248	8,997.00h	3,000.00h	2,127.00h	11,997.00h	2011/05/10
----------------------------------	-----------	-----------	-----------	------------	------------



Aircraft Status



Aircraft: A2-HAN Component: 2350

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: BELL JETRANGER

Description / Part	Installed	Frequency	To Go	When Due	Expected due
--------------------	-----------	-----------	-------	----------	--------------

Heading

T/ROTOR YOKE ASSY Replace

Part:206-011-819-109 9,813.40h 5,000.00h 4,943.00h 14,813.00h 2015/08/15
 S/N:HBFS3634

HYDRALIC PUMP & RES Overhaul

Part:206-076-022-101 S/N:B-3884 7,219.90h 3,600.00h 950.00h 10,820.00h 2009/07/28

SERVO ACTUATOR COLLE Overhaul

Part:206-076-031-107 S/N:RH0445 7,219.90h 3,600.00h 950.00h 10,820.00h 2009/07/28

SERVO ACT CYC L/H Overhaul

Part:206-076-031-107 S/N:RH0366 7,219.00h 3,600.00h 949.00h 10,819.00h 2009/07/28

SERVO ACT CYC R/H Overhaul

Part:206-076-031-17 S/N:RH-141 9,243.00h 3,600.00h 281.00h 10,151.00h 2008/07/23

SERVO ACT SUPPORT Replace

Part:206-001-566-101 0.00h 10,000.00h 130.00h 10,000.00h 2008/05/01

X CYCLIC CONTROL - Not active on this component

INPUT DRIVE SHAFT Inspect

Part:206-040-015-103 9,813.40h 600.00h 543.00h 10,413.00h 2008/12/15
 S/N:AMN11462

INPUT DRIVE SHAFT Inspect

Part:206-040-015-103 2007/12/21 12m 10m 2008/12/20 2008/12/20
 S/N:AMN11462

Component status summary

Position:	N/A	Cycles overhauled:	0
Date Overhauled:	/ /	Cycles since overhaul:	10,761
Hours overhauled:	0.00	Landings overhauled:	0
Hours since overhaul:	9,870.00	Landings since overhaul:	0

Items shown as due if due within 30 days and shown as warning if due within 30 days of the report date: 2008/02/19



All due items



Warning & Due shortly



Warning & Not due



Not active



Aircraft Status



Aircraft: A2-HAN Component: CAE831005

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: ROLLS ROYCE C250 SERIES

Description / Part	Installed	Frequency	To Go	When Due	Expected due
--------------------	-----------	-----------	-------	----------	--------------

engine inspections

✘ ENGINE ASSEMBLY - Not active on this component

● 100 HOUR INSPECTION Inspect

9,813.40h	100.00h	43.00h	9,913.00h	2008/03/14
-----------	---------	--------	-----------	------------

200 HOUR INSPECTION Inspect

9,813.40h	200.00h	143.00h	10,013.00h	2008/05/08
-----------	---------	---------	------------	------------

● 300 HOUR INSPECTION Replace

9,615.60h	300.00h	46.00h	9,916.00h	2008/03/15
-----------	---------	--------	-----------	------------

ENGINE OIL CHANGE Replace

Part:EXXON 2380

9,813.40h	200.00h	143.00h	10,013.00h	2008/05/08
-----------	---------	---------	------------	------------

● COMPRESSOR HALVES Inspect

Part:230571X S/N:SET20087

9,615.60h	300.00h	46.00h	9,916.00h	2008/03/15
-----------	---------	--------	-----------	------------

Compressor

COMPRESSOR Overhaul

Part:6890550 S/N:CAC 35893

8,756.00h	3,500.00h	763.00h	10,633.00h	2009/04/16
-----------	-----------	---------	------------	------------

COMPRESSOR IMPELLER Replace

Part:6876873 S/N:KR89069

8,756.00h	3,550.00h	813.00h	10,683.00h	2009/05/14
-----------	-----------	---------	------------	------------

COMPRESSOR IMPELLER Replace

Part:6876873 S/N:KR89069

9,729c	9,150c	7,080c	17,841c	2018/01/07
--------	--------	--------	---------	------------

✘ 1 STAGE COMP WHEEL - Not active on this component

✘ 2 /3 STAGE COMP WHEEL - Not active on this component

✘ 4 STAGE COMP WHEEL - Not active on this component

✘ 5 STAGE COMP WHEEL - Not active on this component

✘ 6 STAGE COMP WHEEL - Not active on this component

✘ SPUR ADAPTER - Not active on this component

✘ TIE BOLT - Not active on this component

● COMP HALFS Inspect

9,615.60h	300.00h	46.00h	9,916.00h	2008/03/15
-----------	---------	--------	-----------	------------

Turbine

◆ TURBINE ASSY Overhaul

Part:6898735 S/N:CAT 33250

9,813.40h	1,750.00h	511.00h	10,381.00h	2008/11/28
-----------	-----------	---------	------------	------------

TURBINE ASSY

Part:6898735 S/N:CAT 33250

9,243.00h	3,500.00h	1,691.00h	11,561.00h	2010/09/11
-----------	-----------	-----------	------------	------------

1 STAGE WHEEL Overhaul

Part:23073853 S/N:X561007

9,813.40h	1,775.00h	1,718.00h	11,588.00h	2010/09/26
-----------	-----------	-----------	------------	------------

1 STAGE WHEEL Replace

Part:23073853 S/N:X150911

10,708c	3,000c	2,947c	13,708c	2012/04/01
---------	--------	--------	---------	------------

2 STAGE WHEEL Replace

Part:23073854 S/N:X558532

9,813.40h	1,775.00h	1,718.00h	11,588.00h	2010/09/26
-----------	-----------	-----------	------------	------------

2 STAGE WHEEL Replace

Part:23073854 S/N:X558532

10,052c	3,000c	873c	11,634c	2009/05/09
---------	--------	------	---------	------------

3 STAGE WHEEL Replace

Part:23001967 S/N:HX84231

9,813.40h	4,550.00h	2,641.00h	12,511.00h	2012/02/19
-----------	-----------	-----------	------------	------------



Aircraft Status



Aircraft: A2-HAN Component: CAE831005

Hours: 9,870.00 Cycles: 10,761 Landings: 0 Updated: 2008/02/19
 Linked to schedule: ROLLS ROYCE C250 SERIES

Description / Part	Installed	Frequency	To Go	When Due	Expected due
Turbine					
3 STAGE WHEEL Replace Part:23001967 S/N:HX55443	10,052c	6,000c	3,873c	14,634c	2013/07/17
4 STAGE WHEEL Replace Part:6853279 S/N:23068265	9,813.40h	4,550.00h	3,900.00h	13,770.00h	2014/01/15
4 STAGE WHEEL Replace Part:6853279 S/N:23/68265	10,052c	6,000c	5,145c	15,906c	2015/04/26

Components

FUEL CONTROL Overhaul Part:2524644-31 S/N:85310020	8,486.00h	2,500.00h	1,116.00h	10,986.00h	2009/10/28
GOV POWER TURBINE Overhaul Part:2524769-14 S/N:19725	9,230.00h	2,000.00h	1,360.00h	11,230.00h	2010/03/12
FUEL PUMP Overhaul Part:23070459 S/N:AKV0158	7,028.00h	4,000.00h	1,158.00h	11,028.00h	2009/11/20
FUEL NOZZEL Overhaul Part:23077068 S/N:AG60786	9,813.40h	2,500.00h	2,443.00h	12,313.00h	2011/11/01
BLEED VALVE Overhaul Part:23053176 S/N:FF33575	9,216.00h	1,500.00h	846.00h	10,716.00h	2009/06/01
STARTER GENERATOR Overhaul Part:23032-48 S/N:17646	9,421.95h	1,000.00h	552.00h	10,422.00h	2008/12/20

✘ TURBINE - Not active on this component

✘ TURBINE - Not active on this component

GEAR BOX Part:6886442 S/N:CAG 34038	2000/02/02	Once	Done	C/W
--	------------	------	------	-----

Component status summary

Position:	Position No 1	Cycles overhauled:	0
Date Overhauled:	/ /	Cycles since overhauled:	10,761
Hours overhauled:	0.00	Landings overhauled:	0
Hours since overhaul:	9,870.00	Landings since overhauled:	0

Items shown as due if due within 30 days and shown as warning if due within 30 days of the report date: 2008/02/19

All due items
 Warning & Due shortly
 Warning & Not due
 Not active